




## Command Description

The Convert to CAD Points command enables you to select points and convert them to CAD points. It will attach user data to CAD points such as point id, feature code, descriptions, and feature attributes. This enables you to change data that you do not need global positioning on into light weight CAD points.



1. Click in the **Point selection** field and then in a graphic view select the points which you want to convert to CAD points. Click **Options** for additional selection options.
2. Tick the **Relayer** box and pick a layer or create a new layer if you want to move the new CAD points to a different layer.
3. Do either of the following:
  - Click **Apply** to apply the changes and keep the **Convert to CAD Points** command pane open.
  - Click **OK** to apply the changes and close the **Convert to CAD Points** command pane.

The points are now CAD points but still retain point id, feature code, description, and feature attribute information.